

July 1, 2020

VIA ELECTRONIC FILING

Fadi Daye
California Public Utilities Commission
Safety Enforcement Division
505 Van Ness Avenue
San Francisco, CA 94102-3298
fadi.daye@cpuc.ca.gov
ESRB_ComplianceFilings@cpuc.ca.gov

Re: PacifiCorp's (U 901-E) 2019 Annual Report of Inspection Activities Filed Pursuant to General Order No. 165

Per General Order No. 165, PacifiCorp provides the attached 2019 annual report of inspection activities for electric distribution and transmission facilities.

It is respectfully requested that all formal correspondence and Staff requests regarding this matter be addressed to:

By email (preferred): datarequest@pacificorp.com

By regular mail: Data Request Response Center
PacifiCorp
825 NE Multnomah, Suite 2000
Portland, OR 97232

Informal inquiries may be directed to Heide Caswell, Director, Transmission & Distribution Asset Performance, at (503) 813-6216 or Pooja Kishore, Regulatory Affairs Manager, at (503) 813-7314.

Sincerely,



Michael Wilding
Director, Regulation

**ANNUAL REPORT OF INSPECTION ACTIVITIES FILED PURSUANT
TO GENERAL ORDER 165
FOR THE CALENDAR YEAR 2019**

2019 GENERAL ORDER 165 ANNUAL REPORT
Reporting Period: 01/01/19 - 12/31/19
PacifiCorp

Distribution										
District	Overhead Patrol		Overhead Detail		Underground Patrol		Underground Detail		Intrusive	
	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding
Alturas	1,928	0	708	0	62	0	26	0	0	0
Crescent City	4,515	0	1,563	0	1,292	0	634	0	471	0
Tulelake	7,575	0	2,020	0	80	0	53	0	583	0
Yreka	33,667	0	4,622	17 ¹	4,328	132 ²	2,715	3 ³	1,249	0
Total	47,685	0	8,913	17¹	5,762	132²	3,428	3³	2,303	0

Transmission						
District	Overhead Patrol		Overhead Detail		Intrusive	
	Due	Outstanding	Due	Outstanding	Due	Outstanding
Alturas	643	0	3	0	0	0
Crescent City	1,536	0	340	0	0	0
Tulelake	0	0	0	0	0	0
Yreka	6,927	0	508	0	0	0
Total	9,106	0	851	0	0	0

¹ Seventeen (17) incomplete overhead distribution detailed inspections were identified in preparation for this report. These 17 inspections have since been completed in 2020 and are now up to date.

² One hundred and thirty two (132) distribution underground patrol inspections were not completed in 2019. In 2019, PacifiCorp rolled out the use of a new GIS-based inspection tool to facilitate more efficient planning and completion of underground inspections. As a result of both first time user errors and process gaps highlighted with this new tool, 132 inspections were missed. PacifiCorp is currently working to perform both data QA/QC and these inspections are now complete. As part of this review process PacifiCorp has also identified and implemented new processes for additional validation steps to ensure program compliance utilizing the new GIS-based inspections tools moving forward.

³ Three (3) distribution underground inspections were not completed in 2019. In 2019, PacifiCorp rolled out the use of a new GIS-based inspection tool to facilitate more efficient planning and completion of underground inspections. As a result of both first time user errors and process gaps highlighted with this new tool, 3 inspections were missed. PacifiCorp is currently working to perform both data QA/QC and these inspections are now complete. As part of this review process PacifiCorp has also identified and implemented new processes for additional validation steps to ensure program compliance utilizing the new GIS-based inspections tools moving forward.

VERIFICATION

I am Director of Delivery Assurance, and am authorized to make this verification on PacifiCorp's behalf. I am informed and believe that the matters stated in the foregoing document are true.

I declare under penalty of perjury that the foregoing is true and correct.

Executed 1st day of July, 2019 at Portland, Oregon.



Allen Berreth
Director, Delivery Assurance